



BUILDER NOTE:
 WHEN THIS CONDITION OCCURS, PLEASE COORDINATE WITH DOOR SUPPLIER TO VERIFY THAT THE GIRT WILL NOT INTERFERE WITH OVERHEAD DOOR OR DOOR FRAMING.